

ST240PWR 06/04






ITEM	PART	QTY	PART No.
Α	Base ST240PWR	2 ea	Z637BASEXX
В	Lg Wheel 3"	4 ea	Z4011253LG
С	Hex Bolt 5/16" x 2 1/4"	4 ea	Z041312225
D	Locknut 5/16"	8 ea	Z060312NLN
Е	Rubber Rim	2 ea	Z650RIM24D
F	Upright ST240S/P	1 pr	Z638UPRIGHT
G	Eyebolt 3/8" x 2 1/2" (forged)	4 ea	Z040375250
Н	Eyenut 3/8"	2 ea	Z0965375O/S
I	Eyebolt 3/8" x 2 1/4"	6 ea	Z040375225
J	Hex Bolt 5/16" x 3 1/4"	2 ea	Z041312325
K	Pulley	2 ea	Z099UP7086
L	Plastic Cap	2 ea	Z081237BLK
Μ	Snap Link	6 ea	Z411SNAPLK
Ν	Cable 3/16" x 90" Assembly	2 ea	NSPDLXXX
0	Floor Plate (not shown)	2 ea	STFLRPLT
Р	Knob Bolt 1/2" x 4"	2 ea	Z046500400
Q	Winch	1 ea	Z63BLWINCH
R	Winch Handle (not shown)	1 ea	Z649WHAND2
S	Hexnut 3/8" Galv.	2 ea	NSPDLXXX
Т	Locknut 3/8"	6 ea	Z06035-16
U	Hex Bolt 5/16" x 2 3/4"	2 ea	Z041312275
V	Strap 2" x 6'	1 ea	Z5002X6W/H
W	Truss Screw #10 x 1/2"	2 ea	Z052102405


ST240PWR 06/04















CAUTION WHEN MOVING THIS UNIT ALWAYS PUSH NEVER PULL

CAUTION SCREWS MUST BE TIGHT AT ALL TIMES

NOTE: Due to the weight, bases should be moved by adults only!

DO NOT ATTEMPT TO HAND CARRY:

CUSTOMER ADVISORY AND WARNING

Participation in physical education, body copnditioning, athletics, recreational and related activities involve varyiong degrees of accidental injury risks, up to and including those with life threatening potential. Under no circumstances shoul equipment used for these aforeementioned activities be altered, tapered with, or used when damaged. Such equipment should NEVER be used without direct adult supervision and only after examination for damage, wear, proper function and general stability, nor should it be employed for any activity other than that for which it was specifically intended. Such equipment should NEVER be setup, or moved by children. Participants should galways know or be made specifially aware of the risks involved in the activity they are participating in as well as their o0un physical limitations and that of the equipment being used.

DANGER

TIPPING OF UNIT WITHOUT BOLT & NUT INSTALLED & TIGHTENED COULD CAUSE BASE TO SEPARATE FROM UPRIGHT & CAUSE INJURY

WARNING

DO NOT ATTEMPT TO MOVE THIS ASSEMBLY IF NUT OR BOLT IS LOOSE OR MISSING, AS INJURY MAY RESULT

CAUTION

For Safety Remove Handle After Tightening

ST240PWR 06/04

